

Lorah, Steve

From: Davis, Lorraine
Sent: Thursday, December 15, 2011 4:05 PM
To: Lorah, Steve
Subject: Wah Chang drums from 12/13/11 92796-1

CONFIDENTIAL

Steve,

I talked with Vince Brown and Eric Feist of Veolia. Vince is the rep that goes on site. He talked to Fred Hamilton at Wah Chang.

According to Vince:

- *usually ship in 30 gal drums
- *this load was shipped as 55's overpacked into 85's (manifest 000167371VES, 40 drums)
- *55's were not DOT shippable, which is why all of them were overpacked, and, could have some rain water contamination in the 55's
- *milky look to the oil in the drums is probably a water soluble oil
- *the particle size of this load was more finely divided than normal

When I talked to Eric:

- *generator tried to have this material recycled
- *this would be why it was in 55's, not 30's originally
- *drums sat at recycler for a long time before they decided they couldn't handle them
- *drums were in bad condition when they went back to Wah Chang and likely where they were contaminated with rain water (if they actually were)

who is recycler

Let me know if we have to send these back. Do we know how many have already been repackaged?

Lorraine Davis
Customer Coordinator II
Heritage-WTI, Inc.
East Liverpool, OH 43920
330-386-2137 direct / 800-403-4890 toll free
330-386-2167 fax

CONFIDENTIAL

MT Rcvd 4/2/2012